GRAPHIC HORIZON'S INC.

"NATIVE AMERICAN OWNED AND OPERATED"

"PROVIDING EQUIPMENT, SUPPLIES AND SUPPORT TO THE GRAPHICS INDUSTRY SINCE 1991"

FOR SALE

Roland SP-300i
S/N ZAJ1789

EXCELLENT BUY – VERY MINIMAL USE
See Attached Service Report – Call for details.

Description	Sale Price
Roland VersaCAMM SP-300i S/N ZAJ1789 – *Original MSRP $13,995.00* 30" Solvent Printer/Cutter - Included items: Stand, power cord, blade, blade holder, media clamps, cleaning kit, Roland VersaWorks software RIP, User's manual. Interface via Enet 10-100 RJ45 (cable not included) New ink cartridges installed for DEMO & included.	**$8,995.00**
A Roland Certified Technician(s) has performed a complete printer diagnostic and calibrated the printer to factory specifications. Recommended consumable items have been replaced where needed with **Genuine Roland Parts.**	
1. Run diagnostics to confirm that the printer/cutter is operating correctly. **2.** Replace the following applicable items: ***a. Cap tops*** ***b. Pad Cutter (protection strip)*** ***c. Wiper Blades*** ***d. Wiper Scraper*** **3.** Inspect & Clean: a. Print Heads & Capping Station Area b. Linear Encoder Sheet Scale **4.** Check & adjust as needed the following items: a. Drive Belt/Wire Tension b. Cap height c. Limit Position & Cut down d. Linear Encoder Setup/Calibration e. Head Alignment f. Firmware upgrade g. Print/Cut Alignment **5.** Run reports; Service & History	
Options	
GHI-ISO - **I**nstallation & **S**ystem **O**rientation (Tulsa Metro Area)	$495.00
GHI-AOT - **A**dvanced **O**perator **T**raining	$495.00

Subject to Availability - FOB Graphic Horizons, Inc.
All work performed by Roland Certified Technician(s)
Limited Warranty* - 90 Days Parts / 30 Days Labor
GHI Standard Sales Terms & Conditions Apply
Applicable Taxes to be Added

****Limited Warranty: Requires GHI installation service. Covers mechanical parts only. Print Heads, Electronic components, cosmetics and consumables are not included.***

1911 W. RENO ST. • BROKEN ARROW, OK • 74012
TF: (800) 804-5531 • PH: (918) 251-7882 • FX: (918) 251-7881
E-MAIL: GHI@GRAPHICHORIZONSINC.COM

SERVICE REPORT

Model : SP-300i
Version : 1.90
Serial No. : ZAJ1789
Date : 2013/11/14 12:43

==== **Motor group** ====
Motor feed (trip/total [clear]): 10/ 10 hours [0]
Motor scan (trip/total [clear]): 31/ 31 hours [0]
Pump Times (trip/total [clear]): 6,222/ 6,222 times [0]

==== **Head group** ====
Shot Cnt. 1 (trip/total [clear]): 53,098/ 53,098 K shots/nozzle [0]
Shot Cnt. 2 (trip/total [clear]): 37,762/ 37,762 K shots/nozzle [0]
Shot Cnt. 3 (trip/total [clear]): 84,904/ 84,904 K shots/nozzle [0]
Shot Cnt. 4 (trip/total [clear]): 52,118/ 52,118 K shots/nozzle [0]
: H1 H2
Wiping count for head : 248 248 times
Rubbing count for head : 6 6 times
Headrank set count : 0 0 times
Auto cleaning count : 74 74 times
Normal cleaning count : 3 3 times
Medium cleaning count : 4 4 times
Powerful cleaning count: 2 2 times
Protect Head : 34 34 times

==== **Maintenance group** ====
Maintenance Count : 26 times
Total time : 650 hours
Printing time : 0 hours

==== **Wiper group** ====
Wiping count : 248 times
Rubbing count : 6 times
Wiper replace count : 0 times

==== **Print group** ====
Printing time : 27 hours
Print pages : 466 pages

==== **Ink group** ====
Cartridge change(1-4) : 0 0 0 0 times
Change ink type : 0 times

==== **Error group** ====
Service call count : 0 times
Service call history : **** **** **** **** ****
Motor error (feed) : 1 times
Motor error (scan) : 0 times
Low temperature error : 0 times
High temperature error : 0 times
Emergency capping : 0 times
Start uncapped : 0 times

==== **System group** ====
Power on count : 225 times
Power on time : 313 hours
Sleep time : 13,611 hours
Sheet cut count : 362 times
Peck used count : 0 times
Net fault count(pon) : 0 times
Net fault count(cfg) : 0 times

==== **Heater group** ==== PRINT DRYER
Heater used time : 78 75 hours

==== **Cutting group** ====
Cutting time : 25 hours
Disconnect carr. count : 510 times